

ENGINEERING CHANGE NOTICE

DART AEROSPACE LTD

Date: 12.03.16	Job No.:	ADR Yes/No: Y	ADR Date: 11.03.15	ECN #: 12- 550
Product No.: D135-692		Created By: CP	Approved By: <i>[Signature]</i>	
Product Name: Bearpaw		Checked By: <i>[Signature]</i>		

Distribution	Reqd	Resp	Initial / Date
Production Manager / Coord.	Y	LL	<i>MLF 12.03.19</i>
Purchasing Coord.	N		
Production Engineering Coord.	Y	EC/DD	<i>EC 12.03.19</i>

Distribution	Reqd	Resp	Initial / Date
DQA / QA Coord.	N		
QC Coordinator	<i>[Signature]</i> Y	E.D.	<i>[Signature] 12.03.19</i>
Customer Technical Support	Y	MB	<i>[Signature] 12.03.19</i>
Marketing	Y	SW	<i>[Signature] 12.03.19</i>
Customer Order Processing	N		

Reason for Change:

Documents Affected:

Release

DSI 9537 Rev. B

DSI 9587 Rev. A

DSI 9592 Rev. A

PARTS MUST COMPLY ☒ PREVIOUS PARTS SATISFACTORY ☐

#	Quality Assurance Actions	Reqd	Resp	Notes	Complete
1	Notify Previous Customers	N			
2	Notify Eurocopter France	N			
3					

#	Engineering Actions	Reqd	Resp	Notes	Complete
4	Required Documents/Drawings Under Review	N			
5	Update Master Document List (MDL)	Y	MB		<i>12.03.19</i>
6	Update Product Compatibility Matrix	N			
7	Create Eurocopter Form (FEE)	N			
8	Notify TC / FAA of Change	Y	CP		<i>12.03.19</i>
9					

#	Document Control Actions	Reqd	Resp	Notes	Complete
10	Move Electronic Files/Design Journal	Y	KJ		<i>12.03.19</i>
11	Update Product Specification Files	Y	KJ		<i>12.03.19</i>
12	Update Approved/Preliminary Dwg PDF Files	Y	KJ		<i>12.03.19</i>
13	Update Document Record (DR)	N			
14	Update Product Development Summary	N			
15	Update QSI 021 and/or STC Approval List	N			
16	Update Parts / STC Database	N			
17	Update / Verify ARC Database	N			
18	Create / Update Change Record Form / Item Card Database	N			
19	Create / Update PPP's	N			
20	Red Decals required?	N			
21	Update Document Control Database / Laminated Dwgs	N			
22	Update Grey Project / Electronic Binder PDF Files	Y	KJ		<i>12.03.19</i>
23	Update D-Part/M-Drawing/DSI/DEO Master Binders	Y	KJ		<i>12.03.19</i>
24					

Description / Action:

- Per DSI 9592, there should only be (4) D2519 Clamps in a D135-692-011 kit
- Per DSI 9587, replace (8) AN4-15A with (8) AN4-13A bolts in D135-692-011, update kits in stock
- add DSI's to kits in stock

ECN Verified & Complete: *[Signature]*

Date: *2/3/29*